


Inspection Summary Report

GRAVEL EQUIPMENT INC

Inspection: 021727	50 Point	Location: BODE
General		
Stock Number: AT000504	Make: JD	Model: QH-2
Description: KASCO QUICK HITCH CA		
Serial Number: N/A		
Customer Name: TERRY BRENNAN		
Hour Meter: 0	Hour Meter Works: Yes	
2nd Hour Meter: 0	Original Meter: Yes	
Reference Hours: 0		
SAFETY & GENERAL WALKAROUND		
GRAB BARS & STEPS: Very Good		
SHEET METAL: Very Good		
GLASS & MIRRORS: GOOD		
FENDERS & BUMPERS: Very Good		
FRAME, CAR BODY, R.O.P.'S, BOLTS: Very Good		
BOOM, ARM, PUSH ARM: Very Good		
HYDRAULIC GUARDS: Very Good		
FAN GUARDS: Very Good		
UNDERCARRIAGE COMPONENTS: Very Good		
General Condition: Very Good		
PRE START UP		
FUEL LEVEL: Very Good		
ENGINE OIL LEVEL: Very Good		
TRANSMISSION/PT OIL LEVEL: Very Good		
HYDRAULIC OIL LEVEL: Very Good		
FINAL DRIVE/DIFFERENTIAL OIL LEVELS: Very Good		
SWING MACHINE OIL LEVEL: Very Good		
COOLANT LEVEL: Very Good		
GREASE LINES/ZERKS: Very Good		
AXL/FINAL DRIVE LEVEL: Very Good		
PTO LEVEL: Very Good		
DEF/AdBLUE: Very Good		
TIRE CONDITION: Very Good		
RF PSI: Low		
LF PSI: Low		
RR PSI: Low		
LR PSI: Low		
General Condition: Very Good		
CAB INTERIOR		
OPERATORS MANUAL ON MACHINE: YES		

Inspection Summary Report

Inspection: 021727	50 Point	Location: BODE
CAB INTERIOR		
SAFETY WARNING DECALS IN PLACE: YES		
MONITOR PANEL SCREEN: Very Good		
REAR CAMERA FUNCTION: Very Good		
CAB LIGHTS, BULBS, FUSES & SWITCHES: Very Good		
SAFETY SWITCHES: Very Good		
SEAT OPERATION & SAFETY BELT: Very Good		
SEAT SUSPENSION & ADJUSTMENT: Very Good		
FIRE EXTINGUISHER: Very Good		
WIPER FUNCTION & BLADE CONDITION: Very Good		
WINDOWS, LATCHES & GLASS: Very Good		
DOORS, LATCHES, STRIKERS, HOLD-BACK: Very Good		
AC/HEATER OPERATION & LOUVERS: Very Good		
CABIN AIR FILTER: Very Good		
		
HORN & BACK UP ALARM: Very Good		
SWING LOCK: Very Good		
General Condition: Very Good		
START MACHINE		
LEVER CONTROL ACTION & ACCUMULATOR: Very Good		
RIPPER OR WORK EQUIPMENT: Very Good		
BOOM: Very Good		
ARM: Very Good		
BUCKET: Very Good		

Inspection Summary Report

Inspection: 021727	50 Point	Location: BODE
START MACHINE		
LIFT: Very Good		
TILT: Very Good		
DUMP: Very Good		
PARKING BRAKE: Very Good		
BRAKE ACCUMULATOR/PEDAL OPERATION: Very Good		
HEAD LAMPS: Very Good		
RADIO: Very Good		
General Condition: Very Good		
WORK EQUIPMENT & U/C OR TRACK		
GROUND ENGAGING TOOLS: Very Good		
CYLINDERS: Very Good		
IDLER & TRACK ASSEMBLY: Very Good		
ROLLERS & ROLLER GUARDS: Very Good		
SPROCKETS: Very Good		
TRACK CONDITION: Very Good		
General Condition: Very Good		
POWER TRAIN		
HOSES: Very Good		
BELTS: Very Good		
ENGINE: Very Good		
KVGT (TURBO): Very Good		
DOZER PIPING: Very Good		
EGR ASSEMBLY: Very Good		
DPF ASSEMBLY & HEAT SHIELDING: Very Good		
TRANSMISSION & T/C: Very Good		
TRANSMISSION COOLER: Very Good		
FINAL DRIVES OR DIFFERENTIALS: Very Good		
HYDRAULIC COOLER FINS: Very Good		
RADIATOR FINS & RADIATOR CAP: Very Good		
FAN MOTOR & FAN BLADE: Very Good		
BATTERY ELECTROLYTE LEVEL: Very Good		
FUEL TANK CAP: Very Good		
AIR FILTER: Very Good		
General Condition: Very Good		
Overall Condition		
General Condition: Very Good		
<div style="display: flex; justify-content: space-between; align-items: flex-end;"> <div style="text-align: center;">  Customer Signature: _____ </div> <div style="text-align: center;">  Inspector Signature: _____ </div> </div>		

Inspection Summary Report

Inspection: 021727	50 Point	Location: BODE